

**SURVEY &  
REMONUMENTATION**

AUG 2 4 2010

**SECTION**

OSCODA COUNTY REMONUMENTATION  
LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970 \* L C 8 - 2 3 8 2 \*

For corners in \_\_\_\_\_ Located In: \_\_\_\_\_ Corner Code # \_\_\_\_\_  
OSCODA \_\_\_\_\_ REGISTER OF DEEDS  
(County) 08/13/2010 08:51:17AM

JERI WINTON  
OSCODA COUNTY  
REGISTER OF DEEDS  
FEE: \$17.00  
PAGES: 2 RCPT#: 13139  
LC8-238 CORNER RECORDATION

1. Public Land Survey T26N R1E D-7  
T R  
2. Property Controlling S T **APPROVED**  
In Section S T  
3. Miscellaneous S T  
Property in Sec. S T  
County Remonumentation  
Peer Review Group

4. Lot No. \_\_\_\_\_, Recorded Plat *NCC 19 JULY 2010*  
5. Private Claims

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6	5	4				6			2			1
3													
4	7	6	9				10			11			12
5													
6	16	17	16				15			14			13
7	19	20	21				22			23			24
8													
9													
10	30	29	28				27			26			25
11													
12	31	32	33				34			35			36
13													

I, Marvin E. Myers, P.S., in a field survey on June 08, 2010  
do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned  
in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the  
current manual of survey instructions of the United States Department of the Interior, Bureau of Land  
Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5  
above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a  
Court of Law; established, re-established, monumented, re-monumented, recovered, found as  
expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on  
this certificate.

A. Description of original monument and accessories and/or subsequent  
restoration:

D-7 Quarter Section Corner common to Sections 17 & 20 T.26N.-R.1E.

1839 GLO William R Coon, Deputy Surveyor  
Mon - Set 1/4 section post  
Wit: 4" Aspen N60°W 10.5 lks (6.93')  
3" Aspen S57°E 3 lks (1.98')


Part A Continued on back of sheet-->

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:  
D-7 Quarter Section Corner common to Sections 17 & 20 T.26N.-R.1E.

Found USGLO concrete monument; found stump 14" W. Pine (USGLO) S59°W 87.78'; found 14" W. Oak w/ location tag S73°W 98.69';  
found blazed 10" Balsam N31°W 18.34'; found spike E. side 7" dead cherry N50°E 52.10'; found 4" cedar post w/ location tag S05°E  
1.10'; intersection of old trail road Southeast and West (USGLO S88°W 75.24').  
Accepted UGLO monument as a careful and faithful reestablishment of the position of the corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:  
D-7 Quarter Section Corner common to Sections 17 & 20 T.26N.-R.1E.

Mon - Found USGLO concrete monument place two spikes alongside for magnetic attraction  
Wit: S59°W 87.78' found stump 14" W. Pine (USGLO)  
S73°W 98.69' set nail & tag NE side 14" W. Oak with Loc. Tag  
N31°W 18.34' set nail & tag E. side Blazed 10" Balsam  
N50°E 52.10' found nail E. side 7" Dead Cherry  
N32°E 43.40' set nail & tag W. side 16" Maple  
S06°W 50.27' set nail & tag W. side 14" Maple  
S85°E 118.50' face 45" W. Pine  
S05°E 1.10' found 4" Cedar post with Loc. Tag  
South 1.30' set Carsonite Post  
S88°W 75.24' intersection of old trail road SE & West  
South ±30' CL of NW - SE old trail road



*Marvin E. Myers*  
Signed by \_\_\_\_\_  
Surveyor's Michigan License No. 31600

Date July 14, 2010