



LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

**SURVEY &
REMONUMENTATION**

FEB 14 2006

SECTION

For corners in _____ Located in: _____ Corner Code # _____
Lake _____
(County)

- Public Land Survey
I 18 N R 14 W
T N R W
T N R W
T N R W
T N R W
T N R W
T N R W
T N R W
- Property Controlling in Section
S _____
- Miscellaneous Property in Sec.
S _____
S _____
S _____

4. Lot No. _____ Recorded Plat _____
5. Private Claims _____

Register of Deeds Stamp & File Number

A	B	C	D	E	F	G	H	I	J	K	L	M
2	6	5	4	3	2	1						
3												
4	7	8	9	10	11	12						
5												
6	18	17	16	15	14	13						
7												
8	19	20	21	22	23	24						
9												
10	30	29	28	27	26	25						
11												
12	31	32	33	34	35	36						
13												

I, Patrick N. Johnson, in a field survey on November 9, 2005, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 2, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law, established, re-established, monumented, re-monumented, recovered, found as expressed below:

Note: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

F-7: Quarter corner common to Sections 16 & 21, Sweetwater Township, Lake County, Michigan.

A. DESCRIPTION OF ORIGINAL MONUMENT AND ACCESSORIES AND/OR SUBSEQUENT RESTORATION:

1838 S. Sibley, G.L.O.
The corner is an 8" Black Oak

1988 S. Barnett LS 16923
L.C.R.C. recorded Liber 003, Page 0062

Set 5" square concrete monument with brass cap by single proportionate measurement to the original Government Survey. Distance for entire mile fits well with George West distance.

George West (no date)
Shows distance of 5100.5 feet for entire mile. Does not mention a quarter corner.

1983 Clint Cole LS 17615
Survey recorded Liber 02 Page 473

Computed position for corner by single proportionate measurement Did not set corner.

- #1 7" White Oak S44°W 37.53'
- #2 4" White Oak N30°W 23.88'
- #3 6" White Oak N81°E 18.37'
- #4 Carsonite Post North 1'

B. DESCRIPTION OF CORNER EVIDENCE FOUND AND/OR METHOD APPLIED IN RESTORING OR REESTABLISHING CORNER:


I found a 5" square concrete monument stamped "T18N R14W, S16, S21, RLS 16923". The corner is 198 feet North of the centerline of U.S. - 10, and 34 feet North of an East - West woven wire fence (fence runs 30 - 35 feet South of Section line and parallel to it for most of the mile). There is no other occupation at the corner location. I find the corner to be within 0.20 feet of a single proportionate location. The corner fits well with all recovered accessories.

Condition of accessories: #1 - #4, Found in good condition.

C. DESCRIPTION OF MONUMENT FOR CORNER AND ACCESSORIES ESTABLISHED TO PERPETUATE LOCATING THE POSITION OF THE CORNER:

I accepted the 5" square concrete monument as a substantial marker for the corner and is accepted as a careful and faithful reestablishment of the position of the original corner.

- #1 10" White Oak S46°W 37.55' Found 60d spike in Northwest face.
- #2 6" White Oak N28°W 23.81' Found 60d spike in West face.
- #3 8" White Oak N79°E 18.43' Found 60d spike in North face.
- 7" White Pine S10°E 9.79' Set 60d spike in East face.



Signed by Patrick N. Johnson Date 12-12-05

Surveyor's Michigan License No. 47956 Form approved by Michigan State Board of Land Surveyors, Jan. 28, 1971
Revised May 14, 1975
Revised Jan., 1983

Approved by Peer Review Group on 12-12-05
Robert L. Wetherell, County Representative. R.L.W.