

SURVEY &
REMONUMENTATION

FEB 19 2010

SECTION



DELIVERED TO NEWAYGO CO.
02/09/2010 3:36:20 PM

2009 Newaygo County Remonumentation Project

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in
Newaygo
(County)

Located in: Corner Code #

1. Public Land Survey

T14N R11W
T N R W
T N R W

I-8

VOL. 6

227

2. Property Controlling
in Section

S

3. Miscellaneous
Property in Sec.

S

Property in Sec.

S



LINDA M. LANDHEER
NEWAYGO COUNTY REGISTER OF DEEDS
RECEIVED AND RECORDED
02/09/2010 3:40:35 PM

Register of Deeds Stamp & File Number

4. Lot No. Recorded Plat

5. Private Claims

I, Norman L. Ochs, in a field survey on November 2, 2009 do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 2, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

**Note: Not more than 2 corners, all in the same town and range, may be
Recorded on this certificate.**

One Quarter Corner common to Sections 22 and 23, T14N R11W, Goodwell Township.

A. DESCRIPTION OF ORIGINAL MONUMENT AND ACCESSORIES AND/OR SUBSEQUENT RESTORATION:

GLO – J.H. Mullett
4th Quarter 1837

Set quarter Section Post

#1 12" Beech N18°W 13 links (8.58')

#2 14" Pine S41°E 13 links (8.58')

Robert L. Wetherell, R.L.S. # 24624

File No. 3463

January 5, 1980

Set 1" Steel Rod in intersection of fences North – South and East

#3 6" Maple N61°W 18.19'

#4 6" White Pine N69°E 55.91'

#5 10" White Oak S2°W 18.61'

Measured 2629.04' from the East One Quarter Corner to the

Southeast Corner of Section 22, T14N R11W.

B. DESCRIPTION OF CORNER EVIDENCE FOUND AND/OR METHOD APPLIED IN RESTORING OR
REESTABLISHING CORNER:

I found a 1 1/2" x 1'-9" Steel Rod which fits well with Robert L. Wetherell's witness #5 and remains of witness #4. Traces of fence in ground South, East and North. The condition of the witnesses are as follows: #1 thru #3 gone, #4 found White Pine stump 55.91', #5 in good condition.

C. DESCRIPTION OF MONUMENT FOR CORNER AND ACCESSORIES ESTABLISHED TO PERPETUATE
LOCATING THE POSITION OF THE CORNER:

I removed the 1 1/2" x 1'-9" Steel Rod and set a 2 3/4" diameter Harrison Cast Iron Monument 20" long marked "County Survey" #22439 in the ground as a substantial marker for the corner and is accepted as a careful and faithful reestablishment of the position of the original Quarter Corner.

#5 14" White Oak S05°W 18.65'

17" White Oak N30°E 13.15'

4" Ironwood N70°E 18.80'

12" Maple N88°W 22.74'

Set 60d spike with tag over found nail in East face

Set 60d spike with tag in West face

Set 60d spike with tag in Northwest face

Set 60d spike with tag in South face

Signed by

Norman L. Ochs

Norman L. Ochs

Date January 29, 2010

Surveyor's Michigan License No. 22439

Form approved by Michigan State Board of Land Surveyors, Jan. 28, 1971
Revised May 14, 1975
Revised Jan , 1983

Approved by Peer Review Group on October 28, 2009
Norman L. Ochs, County Representative

M.L.O.

