

SURVEY &
REMONUMENTATION

AUG 15 2005

SECTION

2004 Newaygo County Remonumentation Project REC'D AUG 9 2005

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in
Newaygo
(County)

Located in: Corner Code #

1. Public Land Survey

T14N R11W
T N R W
T N R W
T N R W
T N R W
T N R W
T N R W
T N R W

VOL. 4 340

2. Property Controlling
in Section S
3. Miscellaneous S
Property in Sec. S



LINDA M. LANDHEER
NEWAYGO COUNTY REGISTER OF DEEDS
RECEIVED & RECORDED
08/09/2005 11:35:59 AM

Register of Deeds Stamp & File Number

4. Lot No. Recorded Plat
5. Private Claims

I, Norman L. Ochs, in a field survey on January 05, 2005 do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 2, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

Note: Not more than 2 corners, all in the same town and range, may be
Recorded on this certificate.

Section corner common to Sections 34 and 35 of Goodwell Township.

A. DESCRIPTION OF ORIGINAL MONUMENT AND ACCESSORIES AND/OR
SUBSEQUENT RESTORATION:

GLO - JOHN HODGSON 1837

Set quarter section post

#1 28" Pine N15°E 24 links (15.84')

#2 7" Pine N23°W 18 links (11.88')

Closing corner for T13N, R11W is 50 links (33.00') West

Newaygo County Road Commission Sheet

1950's

Axle Shaft

#3 10" Pine N40°E 50.2'

#4 8" White Oak S55°W 55.8'

#5 14" White Oak N15°E 89.0'

#6 10" White Oak S46°W 56.2'

#7 6" White Oak S42°E 60.2'

OVER

B. DESCRIPTION OF CORNER EVIDENCE FOUND AND/OR METHOD APPLIED IN RESTORING OR
REESTABLISHING CORNER:

I found a 3/4" x 12" Iron Pipe in monument box. The corner is in the centerline of North, East and West bituminous roads. The condition of the witnesses are as follows: #1 thru #6 are gone, #7 and #8 are in good condition, #9 NW corner of Section 2 of Big Prairie West 32.89', #10 and #11 did not check.

C. DESCRIPTION OF MONUMENT FOR CORNER AND ACCESSORIES ESTABLISHED TO PERPETUATE
LOCATING THE POSITION OF THE CORNER:

I removed the 3/4" x 12" iron pipe and set a 2 1/2" diameter Harrison cast iron monument 20" long marked "County Survey #22439" in monument box as a substantial marker for the section corner and is accepted as a careful and faithful reestablishment of the position of the original corner.

#7 14" White Oak S45°E 60.19'

#8 12" white Oak S65°W 96.65'

#9 NW corner of Section 2, T13N, R11W is 32.89' West

12" White Pine N45°W 128.92'

10" White Pine N25°E 115.22'

Found spike in SW side

Found spike in SW side

Set 40d spike with tag in SW side

Set 40d spike with tag in West side

Signed by Norman L. Ochs

Norman L. Ochs

Date July 27, 2005

Surveyor's Michigan License No. 22439

Form approved by Michigan State Board of Land Surveyors, Jan. 28, 1971
Revised May 14, 1975
Revised Jan., 1983

Approved by Peer Review Group on July 7, 2005

Norman L. Ochs, County Representative.

