

SURVEY &
REMONUMENTATION

FEB 19 2010



DELIVERED TO NEWAYGO CO
02/09/2010 3:36:20 PM

2009 Newaygo County Remonumentation Project

SECTION

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich P.A. 1970

For corners in

Newaygo
(County)

Located in:

Corner Code #

VOL. 6

229

1 Public Land Survey

T14N R11W

J-7

2. Property Controlling
in Section

S

3. Miscellaneous

S

Property in Sec.

S



LINDA M. LANDHEER
NEWAYGO COUNTY REGISTER OF DEEDS
RECEIVED AND RECORDED
02/09/2010 3:40:35 PM

Register of Deeds Stamp & File Number

4. Lot No. _____

Recorded Plat _____

5. Private Claims _____

I, Norman L. Ochs, in a field survey on November 2, 2009, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 2, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law, established, re-established, monumented, re-monumented, recovered, found as expressed below

**Note: Not more than 2 corners, all in the same town and range, may be
Recorded on this certificate.**

One Quarter Corner common to Sections 14 and 23, T14N R11W, Goodwell Township.

A. DESCRIPTION OF ORIGINAL MONUMENT AND ACCESSORIES AND/OR SUBSEQUENT RESTORATION:

GLO - J.H. Mullett
4th Quarter 1837

A 12" White Oak for Quarter Section Post

Newaygo County Road Commission Sheet
1950's±
Elm Stake and Stone

James G. Knapp, R.L.S. # 25853
1980's±

Set a 5/8" Capped Iron Rod #25853

B. DESCRIPTION OF CORNER EVIDENCE FOUND AND/OR METHOD APPLIED IN RESTORING OR REESTABLISHING CORNER:

I found a 5/8" Capped Iron #25853 (James G. Knapp), and no found witnesses. Found Iron at what appears to be a single proportionate location. A single proportionate location position would be N06°30'W 1.49 feet from his found Iron. The center of an East and West gravel road is 5' South. I measured 2640.07 feet to I-7 and 2639.71 feet to K-7.

C. DESCRIPTION OF MONUMENT FOR CORNER AND ACCESSORIES ESTABLISHED TO PERPETUATE LOCATING THE POSITION OF THE CORNER:

I removed the 5/8" Capped Iron and set a 2 1/4" diameter Harrison cast iron monument 20" long marked "County Survey" #22439 in the gravel road as a substantial marker for the corner and is accepted as a careful and faithful reestablishment of the position of the original Quarter Corner. The centerline of the gravel road is 5' South.

16" Twin Red Oak S24°W 44.91'

Set 60d spike with tag in West face

14" Maple N46°W 30 35'

Set 60d spike with tag in Northeast face

12" Red Oak N43°E 29.17'

Set 60d spike with tag in West face

5" Red Oak S41°E 48.84'

Set 60d spike with tag in Southwest face

Signed by

Norman L. Ochs

Norman L. Ochs

Date January 29, 2010

Surveyor's Michigan License No

22439

Form approved by Michigan State Board of Land Surveyors, Jan 28, 1971
Revised May 14, 1975
Revised Jan , 1983

Approved by Peer Review Group on October 28, 2009

Norman L. Ochs, County Representative.

M.L.O.

