

10

1996 Newaygo County Remonumentation Project

100

LAND CORNER RECORDATION CERTIFICATE
FILING REQUIREMENT of Act 74, Mich. P.A. 1970

'97 FEB 12 PM 4 45

**For corners in
Newaygo**

Corner Code #

T 14N R 11W

 $\frac{8}{Y}$

S	T	R
S	T	R

STR

STR

STR

Recorded Plat _____

100

I, Norman L. Ochis, in a field survey on May 12, 1996, do hereby certify that under requirements of P. A. 74, Michigan P. A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

Note: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

West One Quarter Corner: Section 24, Goodwell Township, Newaygo County, Michigan

A. DESCRIPTION OF ORIGINAL MONUMENT AND ACCESSORIES AND/OR SUBSEQUENT RESTORATION:

G.L.O. J. H. Mullett 1837
8" White Oak \$39°W 21 Links (13.86°)#1
10" White Oak N32°W 14 Links (9.24°)#2

No subsequent surveys of record since G.L.O.

B. DESCRIPTION OF CORNER EVIDENCE FOUND AND/OR METHOD APPLIED IN RESTORING OR REESTABLISHING CORNER:

I was unable to recover any monument at this location. There was no evidence of any occupation lines in this area either. This area had been timbered within the past 15 years destroying any chance of recovering the original bearing trees or monument. I considered this a lost corner and set it by single proportionate method. Distance of 2642.83 feet respectively between section corners and the condition of the recorded witnesses are: #1 and #2 gone.

C. DESCRIPTION OF MONUMENT FOR CORNER AND ACCESSORIES ESTABLISHED TO PERPETUATE LOCATING THE POSITION OF THE CORNER:

Set 4" diameter Harrison cast iron monument 20" long marked "County Surveyor" as a substantial marker for the section corner and is accented as a careful and faithful reestablishment of the original corner.

10" Twin Maple N58°W 12.38' Set spike in Southwest side of tree.
11" Maple N65°E 55.73' Set spike in Northwest side of tree.
7" Maple S44°E 37.36' Set spike in Northeast side of tree.
12" Red Oak S60°W 24.39' Set spike in North side of tree.

Norman L. Nichols

Norman L. Ochs

Surveyor's Michigan License No. 22439

Surveyor's Michigan License No. 22439

Form approved by Michigan State Board of Land Surveyors, Jan 28, 1971
Revised May 14, 1975
Revised Jan., 1983

Approved by Peer Review Group On September 17, 1996
 Norman L. Ochs, County Representative.

22

