

SURVEY &
REMONUMENTATION

FEB 04 2008

IOSCO COUNTY REMONUMENTATION CORNER

SECTION

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

IOSCO

(County)

Located In:

Corner Code #

1. Public Land Survey

T24N R5E

E-4

2. Property Controlling

in Section

3. Miscellaneous

Property in Sec.

S

S

S

S



12/28/2007 1:14:50 PM
STATE OF MICHIGAN - IOSCO COUNTY
FILED
BONITA M. COYLE, REGISTER OF DEEDS



LCRC 2007 83 1

Register of Deeds Stamp & File Number

4. Lot No. _____, Recorded Plat _____
5. Private Claims _____

I, William J. Rigg, P.S., in a field survey on November 9, 2007 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law, established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate

A. Description of original monument and accessories and/or subsequent restoration:

GLO-Set Post

Y. Pine 18" S44W 40 lks

Y. Pine 10" N80E 20 lks

LCRC'S

1986, Lapham found and accepted 1-1/2" pipe

1991, Shellenbarger found and accepted same 1-1/2" pipe

Surveys:

1976 John Oliver found 1-1/2" pipe

1994 Kobs 14097, found 1-1/4" pipe

2001 Rigg 41108, found pipe per lorc 91-5

2003 Rigg 41108, found 1-1/2" pipe

2003 Rigg 41108, found 1-1/2" pipe

William Woods corner history report

Subdivisions:

Chain Lake Health Resort references corner

Blueberry Hill references corner

Amended Plat of Lots 10-20, Block 4 and vacated park, Chain Lake

Health Resort references corner.

Amended Plat of Lots 15, 16 and Outlot 4, Block 8 and vacated

portion of circle Drive and the Beach of Chain Lake Health Resort.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner.

Found 1-1/2" Pipe in position as shown on LCRC's, surveys, and subdivisions. Accepted 1/1/2" pipe as best available position for corner.

ACCEPTED BY THE IOSCO COUNTY
SURVEY FEE GROUP AS THE
OFFICIAL CORNER UNDER P.A.
345 OF 1980 AT A MEETING
HELD ON 11-06-07

William E. Wood

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:


Replaced pipe with 5/8" terod and remon cap.

Found S60°W 18.61' 4" Oak

Found N75°W 55.0' Twin 15" Oak

Found N05°W 31.41' 20" Oak

Found N75°E 92.55' Power Pole



Signed by *[Signature]*

Surveyor's Michigan License No. #41108

Date November 9, 2007