

**SURVEY &
REMONUMENTATION**

FEB 04 2008

SECTION IOSCO COUNTY REMONUMENTATION CORNER
LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

IOSCO
(County)

Located in:

Corner Code #

1. Public Land Survey

T24N R5E F-3
T___R___
T___R___
T___R___
T___R___
T___R___
T___R___
T___R___

**2. Property Controlling
in Section**

S___
S___
S___
S___

3. Miscellaneous

Property in Sec. S___R___



12/28/2007 1:14:50 PM
STATE OF MICHIGAN - IOSCO COUNTY
FILED
BONITA M. COYLE, REGISTER OF DEEDS



LORC 2007 . 92

Register of Deeds Stamp & File Number

4. Lot No. _____, Recorded Plat _____
5. Private Claims _____

I, **William J. Rigg, P.S.**, in a field survey on **November 9, 2007** do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate

A. Description of original monument and accessories and/or subsequent restoration:

GLO:

Cedar 10" for 1/4 section corner

LORC'S

1976, John Oliver, Found 3/4" pipe in conc.

Surveys:

1977 John Oliver, references corner

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found concrete monument in position as shown on LORC's and surveys. Accepted concrete monument as best available position for corner


ACCEPTED BY THE IOSCO COUNTY
SURVEY PEER GROUP AS THE
OFFICIAL CORNER UNDER P.A.
345 OF 1990 AT A MEETING
HELD ON 11-06-07

William J. Rigg

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Left conc. monument as found:

Found S10°W 12.58' 10" Cedar
Found N85°W 6.51' 10" Cedar
Found N05°E 13.52' 6" Cedar
Set N75°E 15.53' 10" Elm
Found North 83°+/- 10' Creek



Signed by

William J. Rigg

Surveyor's Michigan License No. #41108

Date November 9, 2007