

SURVEY &
REMONUMENTATION

FEB 04 2008

IOSCO COUNTY REMONUMENTATION CORNER
LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

IOSCO

(County)

Located in:

Corner Code #



12/28/2007 1:14:50 PM
STATE OF MICHIGAN - IOSCO COUNTY
FILED
BONITA M. COYLE, REGISTER OF DEEDS

1. Public Land Survey

T24N R5E

G-5

T___R___
T___R___
T___R___
T___R___
T___R___
T___R___
T___R___

2. Property Controlling

S___

in Section

S___

3. Miscellaneous

S___

Property in Sec.

S___



LCRC 2007 . 68

Register of Deeds Stamp & File Number

4. Lot No. _____, Recorded Plat _____
5. Private Claims _____

I, William J. Rigg, P.S., in a field survey on November 9, 2007 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate

A. Description of original monument and accessories and/or subsequent restoration:

GLO: Set Pos,
Y. Pine 16" N58E 13 lk,
Y. Pine 20", N89W 40 lks
LCRC'S
1986, LCRC 86-07 find 1/2" bar and cap
1994, Lapham find 5/8" iron
2004 Lapham set aluminum pipe with brass cap
Surveys:
1940's RJ Cooke found & witnessed corner
1973 James Campbell find conc. mon
1985 Norstar Surveys found 1/2" rebar

1986 Miller references corner
2000 NE land surveys find 1/2" bar with lapham cap
2000 Rigg Land Surveying find 1/2" bar with lapham cap
2004 lapham set brass capped mon
William Woods corner history report
Subdivisions:
Lees subdivision notes corner
Supervisor's Plat of Jose Lake Resort Notes corner
Supervisor's Plat of Jose Lake Resort No. 2 Notes corner
Lisa's Lagoon notes corner

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:


Found 2-1/2" pipe with brass cap, position agrees with surveys, subdivisions and lerc's, no other conflicting corners or positions were found. Accepted pipe and cap as best available evidence for corner.

ACCEPTED BY THE IOSCO COUNTY
SURVEY PEER GROUP AS THE
OFFICIAL CORNER UNDER P.A.
345 OF 1990 AT A MEETING
HELD ON 11-08-07

William E. Wood

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Left 2-1/2" x 36" aluminum pipe with brass cap
S57W 54.18 spike in 10" White Pine
N55W 78.22 spk in 10" Oak
S75E 64.84 spk in 8" White Pine
S23E 102.14 spk in 14" White Pine



Signed by *William J. Rigg*

Surveyor's Michigan License No. #41108

Date November 9, 2007