
FEB 10 12 09 PM 189

1868 376 MIE 692

Bin h Cayle



CERTIFIED SURVEY MAP

PAGE 2 OF 4

LEGAL DESCRIPTIONS

PARCEL A: Part of the North ½ of Section 6, T.24N., R.5E., Plainfield Township, Tosco County, Michigan, described as commencing at the Northwest corner of said Section 6, which is also the corner common to Iosco, Ogenaw, Oscoda, and Alcona Counties; thence S.00°58'34"E., along the West line of said Section 6 and centerline of South Branch Road (66 feet wide right-of-way), 726.01 feet to the POINT OF BEGINNING; thence continuing S.00°58'34"E., along said West line and centerline, 198.01 feet; thence N.89°21'00"E., 1630.42 feet; thence N.01°09'32"W., 220.19 feet; thence N.89°16'46"E., 2437.75 feet to a point of the North-South 1/8 line of the NE¼ of said Section 6; thence N.01°20'35"W., along said 1/8 line, 702.48 feet to the North line of said Section 6; thence S.89°16'46"W., along said North line, 1318.66 feet to the North ½ corner of said Section 6; thence S.89°21'00"W., along said North line, 1316.86 feet to the North-South 1/8 line of the NW¼ of said Section 6; thence S.01°09'32"E., along the 1/8 line of said NW¼, 726.03 feet; thence S.89°21'00"W., 1429.79 feet to the point of beginning, containing 50.05 acres subject to and together with the rights of ingress, egress, and public utilities in the westerly 33 feet thereof in South Branch Road, and any other easements of record.

PARCEL B: Part of the North ½ of Section 6, T.24N., R.5E., Plainfield Township, Iosco County, Michigan, described as commencing at the Northwest corner of said Section 6, which is also the corner common to Iosco, Ogemaw, Oscoda, and Alcona Counties; thence S.00°58'34"E., along the West line of said Section 6 and centerline of South Branch Road (66 feet wide public right-of-way), 924.02 feet to the POINT OF BEGINNING; thence continuing S.00°58'34"E., along said West line and centerline, 198.00 feet; thence N.89°21'00"E., 1631.05 feet; thence S.01°09'32"E., 325.82 feet; thence N.88°18'18"E., 1120.90 feet to an 1/8 corner; thence continuing N.88°18'18"E., along the East-West 1/8 line of the NE¼ of said Section 6, 1319.14 feet to the center 1/8 corner of the NE½ of said Section 6; thence N.01°20'35"W., along the North-South 1/8 line of the Northeast ¼ of said Section 6, 702.48 feet; thence S.89°16'46"W., 2437.75 feet; thence S.01°09'32"E., 220.19 feet; thence S.89°21'00"W., 1630.42 feet to the point of beginning, containing 47.90 acres subject to and together with the rights of ingress, egress, and public utilities over the westerly 33 feet thereof in South Branch Road, and any other easements of record.

Survey for: Harold Bannister

Location: Sec. 6, T24N, R5E

×

SINTE OF MICHIGAN

KEYNO J.

LAND SURVEYOR

30101

* SHELLENBARGER

Scale: 1" = 500'

Date: 02/08/89

Ву: клѕ

Job No.: 89-8

I hereby certify the following: this survey was performed and map prepared by me, or under my direct supervision; the ratio of closure of latitudes and departures resulting from field work is one foot in 5686 feet; the requirements of Act No. 132, Public Acts of 1970, and Act No. 24, Public Acts of 1988, have been complied with.

Keyno J. Shellenbarger, Ph.O., P.E., L.S. L.L.S. No. 30101

SHELLENBARGER ENGINEERING AND SURVEYING, P.C. 5000 Northwind Office Park, Suite 224, East Lansing, Michigan 48823 Phone: (517) 337-8270

CERTIFIED SURVEY MAP

PAGE 3 OF 4

PARCEL C: Part of the North ½ of Section 6, T.24N., R.5E., Plainfield Township, Iosco County, Michigan, described as commencing at the Northwest corner of said Section 6, which is also the corner common to Iosco, Ogemaw, Oscoda, and Alcona Counties; thence S.00°58'34"E., along the West line of said Section 6 and centerline of South Branch Road (66 feet wide public right-of-way), 1122.02 feet to the POINT OF BEGINNING; thence continuing S.00°58'34"E., along said West line and centerline, 198.00 feet; thence N.89°21'00"E., 1431.68 feet to a point on the North-South 1/8 line of the NW¼ of said Section 6; thence s.01°09'32"E., along said North-South 1/8 line, 1444.77 feet to the 1/8 corner on the East-West centerline of said Section 6; thence N. 87°41'20"E., along the East-West centerline of said Section 6, 1224.77 feet to the center of said Section 6; thence N.01°19'17"W., along the North-South centerline of said Section 6, 1299.10 feet to an 1/8 corner; thence S.88°18'18"w., 1120.90 feet; thence N.01°09'32"W., 325.82 feet; thence S.89°21'00"W., 1631.05 feet to the point of beginning, containing 47.68 acres subject to and together with the rights of ingress, egress, and public utilities over the westerly 33 feet thereof in South Branch Road, and any other easements of record.

WITNESSES TO SECTION AND QUARTER-SECTION CORNERS

NW CORNER OF SECTION 6, T.24N., R.5E. (CORNER COMMON TO IOSCO, OGEMAW, ALCONA, AND OSCODA COUNTIES):

Found witnesses as recorded in Liber 1 of Corner Record Certificates, Page 135, Alcona County Records. Corner monument has been buried with several feet of aggregate and pavement. Raised with $2\frac{1}{2}$ " dia. aluminum cap in steel pipe.

East 33.17 feet to Bearing Post.
 S.58°W. 84.22 feet to power pole.

3. N.47°W. 115.03 feet to SE corner of house.

4. S.45°E. 61.80 feet to nail with LS 30101 tag in SW face of 30" diameter oak tree.

NORTH & CORNER OF SECTION 6, T.24N., R.5E. (ALSO THE SOUTH & CORNER OF SECTION 31, T.25N., R.5E.):

Found U.S. General Land Office monument stamped \$ S 31. Original GLO notes indicate the East line of Section 6 closed on the standard corner. Therefore, there were no double corners set along the North line of Section 6.

 South 10.24 feet to nail with LS 30101 tag in West face of 4" dia. oak tree.

2. N.50°E. 24.51 feet to nail with LS 30101 tag in West face of 21" dia. maple tree.

3. N.30°E. 21.61 feet to nail with LS 30101 tag in East face of 12" dia. maple tree.

Survey for: Harold Bannister

Location: Sec. 6, T24N, R5E

ATE OF MICHIGAN

KEYNO J

SHELLENBARGER

LAND

No. 30101

Scale: 1" = 500'

Date: 02/08/89

By: KJS

Job No.: 89-8

I hereby certify the following: this survey was performed and map prepared by me, or under my direct supervision; the ratio of closure of latitudes and departures resulting from field work is one foot in _______ feet; the requirements of Act No. 132, Public Acts of 1970, and Act No. 24, Public Acts of 1988, have been complied with.

Keyno J. Shellenbarger, Ph. B., P.E., L.S. L.L.S. No. 30101

SHELLENBARGER ENGINEERING AND SURVEYING, P.C. 5000 Northwind Office Park, Suite 224, East Lansing, Michigan 48823 Phone: (517) 337-8270

CERTIFIED SURVEY MAP

PAGE 4 OF 4

NE CORNER OF SECTION 6, T.24N., R.5E. (ALSO THE SE CORNER OF SECTION 31, T.25N.,

Found U.S. General Land Office monument. Original GLO notes indicate the East line of Section 6 closed on the standard corner.

- 1. N.45°W. 9.45' to nail with LS 30101 tag in East face of 15" dia. maple (double) tree.
- S.30°E. 5.89' to nail with LS 30101 tag in NE face of 12" dia. maple tree.
- East 14.24' to nail with LS 30101 tag in North face of 10" dia. maple

- WEST $\frac{1}{4}$ CORNER OF SECTION 6, T.24N., R.5E.: Raised monument with $2\frac{1}{2}$ " dia. aluminum cap in steel pipe. 1. N.57°E. 80.45' to nail and tag in posted bearing tree.
 - S.52°W. 83.98' to nail and tag in NE face of power pole, posted as a
 - bearing witness. S.60°E. 40.73' to nail with LS 30101 tag in North face of 12" dia. ash tree.

CENTER OF SECTION 6, T.24N., R.5E.:

Set 21 dia. aluminum cap in 2 dia. steel pipe.

- North 2.88 feet to nail with LS 30101 tag in NW face of 4" dia. cedar tree. South 27.94 feet to nail with LS 30101 tag in East face of 10" dia. cedar
- 2. tree
- N.20°W. 26.77 feet to nail with LS 30101 tag in East face of 12" dia. cedar tree.

SW CORNER OF SECTION 6, T.24N., R.5E.: Raised corner with $2\frac{1}{2}$ " dia. aluminum cap in 2" dia. steel pipe. Used centroid figure created by swinging arcs from posted bearing witnesses.

- S.70°W. 59.35 feet (posted as 59.41) to nail/tag in NW face of 12" dia. maple tree.
- 2. East 33.03 feet (posted as 32.91) to nail/tag in N. face of bearing post.
- S.44°E. 60.73 feet (posted as 60.83) to nail/tag in N. face of 10" dia. maple tree.

SE CORNER OF SECTION 6, T.24N., R.5E.: Set $\frac{1}{2}$ " rerod with LS 30101 cap.

- N.30°W.5.45 feet to nail with LS 30101 tag in East face of 5" dia. cedar tree.
- East 11.12 feet to nail with LS 30101 tag in N. face of 10" dia. cedar
- South 8.91 feet to nail with LS 30101 tag in West face of 10" dia. cedar tree
- South 396 feet to centerline of 5 foot wide stream.

Survey for: Harold Bannister Location: Sec. 6, T24N, R5E

*

SATE OF MICHIGAN

KEYNO J.

SUBVEYOR

1(c. 30101

lich &

*

*

0

* SHELLENBARGER

Scale: 1" = 500'

Date: 02/08/89

By: KJS

Job No.: 89-8

I hereby certify the following: this survey was performed and map prepared by me, or under my direct supervision; the ratio of closure of latitudes and departures resulting from field work is one foot in 5686 feet; the requirements of Act No. 132, Public Acts of 1970, and Act No. 24, Public Acts of 1988, have been complied with.

> luckenbar

SHELLENBARGER ENGINEERING AND SURVEYING, P.C. 5000 Northwind Office Park, Suite 224, East Lansing, Michigan 48623 Phone: (517) 337-8270

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

89-05 Feb 10 12 11 PH 109

Brita Mi Cayle

For corners in	rining riequii	ement of Act 14, mon. 1.	Coreta the Cayle
IOSCO	Located Inc	Corner Code ##	REGISTER OF DEFE
(County)	Located In:	Corner Code 44	TOSCO COUNTY, MICH.
 Public Land Survey 	T 24N R 5E	A-1	
	T 24N R 5E	_B-1	
	T 24N R 5E	_C-1	
	T 24N R 5E	A-2	
	S T R		
	S T R		강화 이 어느는 마느 등이 그리고 하였다.
	S T R		Register of Deeds Stamp & File Number
Property in Sec.	S T R		
4. Lot No, Rece	orded Plat		A B C D E F G H I J K L
5. Private Claims			,
	D-1		* - 7 8 9 10 11 12-
Keyno Shellenbargen	a field survey on Febru	ary 4 , 19 89	5
do hereby certify that under require in lines 1 and 2 above were in co	ements of P.A. 74, Michigan P.A	of 1970, the corner points ment	n the 6 18 17 16 15 14 13
current manual of survey instructi	ons of the United States Depa	rtment of the Interior, Bureau of	Land 7
Management or by a decree of a Co	ourt of Law and/or that the corn	er points mentioned in lines 3, 4	and 5 8 19 20 21 22 23 24
above were in conformance with the	he rules of the Michigan Board	of Land Surveyors or by a Decre	eofa a
Court of Law; established, re-e	stablished, monumented, re-	-monumented, recovered, four	nd as
expressed below:			
NOTE: Not more than 4 corr	ners, all in the same town a	and range, may be recorded	
on this certificate.			12 31 32 33 34 35 36
			13
 A. Description of original mo 	nument and accessories a	nd/or subsequent restoration	
A-1 No evidence of or	riginal monument was	s found.	STATE OF MICHICAN
B-1 No evidence of or	riginal monument was	s found.	Simon
C-1 No evidence of or	riginal monument wa	s found.	A*/ KEYNO J. *\
A-2 No evidence of or	riginal monument was	s found.	* SHELLENBARGER: *
			Li LAND
			SURVEYOR A
			30101
			18 CO
			TAND SO
B. Description of corner evid	dance found and/or mother	applied in reclaring or rees	tablishing corner:
B. Description of corner evid	Table Ogomora Ala	one and Occode Cour	ties. Found witnesses as recorded
A-1: Corner common to	Page 135	Alcono Co. Bogorda	B-1: Found US GLO Brass Cap in
in Liber 1 of Corner	Records, Page 135,	eter indicate the F	line of Section 6 closed on the
concrete, stamped 7	531. Orginal Gib ii	M line of Section 6	there are no double corners
			, there are no double corners.
C-1: Found US GLO Brass			
Original GLO notes in			
Section 6 closed on t		61-U	
closing corner was se	et nere.		male beauing and distance
		ing tree and posted	power pole bearing and distance.
witnesses to corners	•		
C. Description of monument	for corner and accessorie	s established to perpetuate I	ocating the position of the corner:
A_1. Paised monument	with 21" dia alum.	cap in 2" dia, stee	el pipe. 1. E. 33.17' to bearing
most. 2. S.58°W. 84.	22' to pp. 3. N.47°	W. 115.03' to SE con	mer of house. 4. S.45°E. 61.80' to
nail with IS 30101 t	ag in SW face of 30	" dia. Oak tree.	B-1: N. 4 Cor. Sec. 6: Brass Cap in
concrete 1 S 10.2	4' to mail with IS	30101 tag. W. face 4	1" dia. Oak. 2. N.50°E. 24.51' to
pail with IS 30101 t	ag W. face 21" dia.	Maple, 3, N,30°E, 2	21.61' to mail with LS 30101 tag E.
face 12" dia Manle	C-1: NE Cor Sec	6. Brass Can in cond	rrete. 1. N.45°W. 9.45' to nail
with IS 30101 tag E	face 15" dia, doub	ole Maple, 2, S,30°E	. 5.89' to hall with LS 30101 tag
in NE face of 12" Ma	Dle 3 E 14-24' t	o nail with LS 3010	l tag in N. face 10" dia. Maple.
A-2:W + Cor. Sec. 6:	Raised monument wi	th 21" dia. alum. ca	ap in 2" dia. steel pipe.
1 N 57°F 80 45' to	nail/tag in posted	Rearing tree. 2. 9	5.52°W, 83.98' to nail/tag in NE
face of power pole	posted as bearing v	vitness. 3. S.60°E.	40.73' to nail with LS 30101 tag
in N Face of 1211 31	- Neh Aron		
Signed by	T. Thillinkan	Dala	FEBRUARY 9, 1989
Signed by/ujno/	1. Anniemony	Date _	FEBRUARY 9, 1989 FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28.
Surveyor's Michigan License	No. 30107		FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28. 1
,			REVISED MAY 14. 1
			MENSED VAN.

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

F	:-	Filing Require	ment of Act 74, Mich. P.A. 19	70 Brier the Carle
For corn IOSC			00-4	RECISTER OF DEEDS
	(County)	Located In:	Corner Code ##	IOSCO COUNTY, MICH.
	ic Land Survey	T 24N R 5E_ T 24N R 5E_ T 24N R 5E_ T R 5E_ T R	_B-2 _A-3	
3. Misc	ection cellaneous perty in Sec.	S T R S T R S T R		Register of Deeds Stamp & File Number
4. Lot	No	, Recorded Plat		- ABCDEFGHIJKLA
5. Priva	ate Claims			2 4 5 4 3 2 1
do hereb in lines in lines current r. Manager above we Court of expresse NOTE: A. De: B-2: A-3: C-3:	yeerily that under and 2 above were annual of survey in: nent or by a decree re in conformance Law, established do below: Not more than 4 on this certifica scription of origin Center of S No evidence accessories	al monument and accessories and section 6: This corner was of original monument was of original monument was a construction of the section of	of 1970, the corner points mentioned of unles therefore as required in the ment of the Interior, Bureau of Land points mentioned in lines 3.4 and 5 Land Surveyors or by a Decree of a conumented, recovered, found as drange, may be recorded for subsequent restoration: as not set during the case found. Located streampplied in Located streampplied in restoring or reestablishapplied in restoring or r	
B-2:	centerline	of Section 6.		enterline with East-West
A-3:	of figure of	created by swinging post	ed arc distances.	
C-3:				ins from stream 15 ROREMICHICAL ** KEYNO J. ** SHELLEHDARAGER ** ** LAND SURVEYOR ** ** No. 30101
C. De B-2:				h 2.88' to nail/tag 44NNO SWE
A-3:	(posted as	59.41') to nail/tag NW	face 12" dia. maple. bearing post. 3. S.	pipe. 1. S.70°W. 59.35' 2. East 33.03' (posted 44°E. 60.73' (posted as
C-3:	Set ½" dia	dar. 2. East 11.12' t	on ail/tag N. face 10" Conail/tag N. face 10" Cedar. 4. South 39	6' to centerline 5' wide
Signed	by Key	no / Shulenbarger	Date	EBRUARY 9, 1989
Survey	or's Michigan Lic	cense No	FOR	IM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAM. 28, 11 REVISED MAY 14, 17 REVISED JAM., 1