


SURVEY &
REMONUMENTATION

SEP 11 2007

SECTION

OSCODA COUNTY REMONUMENTATION
LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970 *



JERI WINTON

For corners in
OSCODA
(County)

Located In: Corner Code #

1. Public Land Survey

T26N

R1E

I-4

2. Property Controlling
in Section

S

S

3. Miscellaneous
Property in Sec.

S

S

4. Lot No. _____, Recorded Plat
5. Private Claims

APPROVED

OSCODA COUNTY
REGISTER OF DEEDS
FEE: \$17.00
PAGES: 2 RCPT#: 5761
LC8-123 CORNER RECORDATION

Register of Deeds Stamp & File Number

Peer Review Group

1912 OSCODA COUNTY SURVEYOR C.O. SEELEY

I, Marvin E. Myers, P.S., in a field survey on April 24 2007, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

I-4 Quarter Section Corner common to Sections 10 & 11 of T.26N.-R.1E.

1839 GLO William R. Coon Deputy Surveyor

Mon.- Set quarter Section post

Wit: Spr Pine 6" N11°E 7 lks (4.62)

Spr Pine 6" N72°W 19 lks (12.54)

1912 Oscoda County Surveyor C.O. Seeley

Mon.- Set ¼ post bet Sec 10-11 From pipe driven at post

Wit: Marked NBT Spr pine N85 ½°E 48 ½ lks (32.01)

Part A continued on back: →

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

I-4 Quarter Section Corner common to Sections 10 & 11 of T.26N.-R.1E.

Found USGLO concrete monument with brass cap with 1" T-iron along side for magnetic attraction; found 8" J Pine N02°E 58.75; found nail & tag #13584 in Power pole N44°E 55.16; found large spike and scribed blaze in 8" J Pine S58°E 76.98; found Cedar Post West 1.3; found 4" R Pine S27°W 117.15; found carsonite post East 0.5; found 10" J Pine stump S34°W 72.93; found 14" J Pine S40°W 75.2 Accepted USGLO monument as a careful and faithful reestablishment of the position of the corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

I-4 Quarter Section Corner common to Sections 10 & 11 of T.26N.-R.1E.

Mon - USGLO concrete monument with brass cap left in place

Wit: N02°E 58.75 Found 8" J Pine

N44°E 55.16 Found nail & tag #13584 in Power pole


S58°E 76.98 Found large spike and scribed blaze in 8" J Pine

West 1.3 Found Cedar Post

S27°W 117.15 Found 4" R Pine

East 0.5 Found carsonite post

S40°W 75.2 Found 14" J Pine



Signed by Marvin E. Myers
Surveyor's Michigan License No. 31600

Date August 21, 2007