


SURVEY &
REMONUMENTATION

SEP 11 2007

SECTION

OSCODA COUNTY REMONUMENTATION
LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970*



JERI WINTON

For corners in
OSCODA _____
(County)

Located in: Corner Code #

OSCODA COUNTY
REGISTER OF DEEDS
08/29/2007 10:09:08AM
FEE: \$17.00
PAGES: 2 RCPT#: 5761
LCB-124 CORNER RECORDATION

1. Public Land Survey T26N R1E L5
T T T T T
2. Property Controlling S
in Section S S S S S
3. Miscellaneous S
Property in Sec. S

APPROVED

R County Remonumentation
Peer Review Group

Register of Deeds Stamp & File Number

4. Lot No. _____, Recorded Plat
5. Private Claims

1122 25 AUG 07

I, Marvin E. Myers, P.S., in a field survey on April 24 20 07,
do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned
in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the
current manual of survey instructions of the United States Department of the Interior, Bureau of Land
Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5
above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a
Court of Law; established, re-established, monumented, re-monumented, recovered, found as
expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on
this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

I-5 Section Corner common to Sections 10, 11, 14, & 15 of T.26N.-R.1E.

1839 GLO William R. Coon Deputy Surveyor 1885 Oscoda County Surveyor John Randall

Mon.- Set post Corner Sections 14, 15, 10, 11 Mon.- Not given

Wit: W Pine 18" N26°W 16 lks (10.56) Wit: None given

W Pine 18" S65 ¾°E 6 lks (3.96)

Part A continued on back:→

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

I-5 Section Corner common to Sections 10, 11, 14, & 15 of T.26N.-R.1E.

Found USGLO concrete monument with brass cap; found 5" White Pine N53°W 20.86; found 6" W Pine stump N89°W 21.84; found
nail S. side Cedar Post East 33.07; found 6" W Pine (lying down) N70°E 51.34 Accepted USGLO monument as the best available
evidence of the position of the Original Government Corner. Corner is in Knott Road

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:
I-5 Section Corner common to Sections 10, 11, 14, & 15 of T.26N.-R.1E.


Mon - USGLO concrete monument with brass cap left in place with Iron alongside for magnetic attraction.

Wit: East 33.07 Found nail S. side Cedar Post

S75°W 31.59 Nail & tag 10" J Pine

N58°E 66.52 Nail & tag 6" J Pine

S50°E 31.25 Top of 16" CMP culvert



Signed by Marvin E. Myers
Surveyor's Michigan License No. 31600

Date August 7, 2007