

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

Oscoda _____
(County)

Located in:

Corner Code #

1. Public Land Survey

T	26N	R	2E	A - 9
T		R		
T		R		
T		R		
T		R		
T		R		
T		R		
T		R		
T		R		
T		R		

2. Property Controlling

S

in Section

S

3. Miscellaneous

S

Property in Section

S

4. Lot No. _____, Recorded Plat _____

5. Private Claims _____

I, Marvin E. Myers, in a field survey on June 5, 1995
do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned
in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current
manual of survey instructions of the United States Department of the Interior, Bureau of Land
Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and
5 above were in conformance with the rules of the Michigan Board of Professional Surveyors or by a
Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found
as expressed below:

**NOTE: Not more than 4 corners, all in the same town and range, may be recorded
on this certificate.**

A. Description of original monument and accessories and/or subsequent restoration:

GLO-L. Clawson May 1839

Mon-Post

WIT: 5" Spruce S69½°W 35 lks.
9" Spruce N62°W 67 lks.
10" Spruce S34°E 20 lks.
8" Aspen N42°E 19 lks.

John Randall Dec. 27, 1887

Mon-Unknown

WIT: 8" Spruce S83°W 1.85 chs.

Cedar cor. fence post N39°W 89 chs.

GLO-G. Veal Oc. 1935

Mon-Intersection of roads accepted as
best available evidence; Set Conc. Mon.
with Brass Tablet

WIT: 10" J. Pine N60½°E 70 lks.
14" B. Oak N78 3/4°W 61½ lks.
6" J. Pine S44°E 110½ lks.
7" J. Pine S36½°W 104 lks.

L.1 of plats, pg. 25 G. Henning Mar. 1940

Mon-Unknown

WIT: None given

MSHD MKW 1958

Mon-Brass Cap

WIT: 18" Oak N79°W 41.89'
Telephone pole N44°E 46.97'
SW Cor. Bldg. S52°E 70.98'

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found ½" Bar & Cap. Found USGLO concrete monument under ½"x4" bar & cap. Accepted as the best available
evidence of the re-establishment of the Original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Mon- USGLO concrete monument.

WIT: Fd. 18" Norway N59°E 117.14'
Fd. 20" Tw. Oaks N85°W 41.85' (recorded as 40.85')
Fd. 4" Norway N51°W 82.91'
Fd. 15" Oak S72°W 160.80'

APPROVED

County Remonumentation
Peer Review Group

REC/31 JUL 95
JULY



Signed by

Marvin E. Myers

Date

July 31, 1995

Surveyor's Michigan License No. 31600

Liber 4 pg. 64

STATE OF MICHIGAN
OSCODA COUNTY
FILED

2 AUG 95 9:36 A.M.

PATSY J. PETERS
REGISTER OF DEEDS

Register of Deeds Stamp & File Number

A	B	C	D	E	F	G	H	I	J	K	L	M
2	6	5	4	3	2	1						
3												
4	7	8	9	10	11	12						
5												
6	18	17	16	15	14	13						
7												
8	19	20	21	22	23	24						
9												
10	30	29	28	27	26	25						
11												
12	31	32	33	34	35	36						
13												

LCRC L.3, pg. 258

G. Wilson Sept. 21, 1992

Mon-Fd. GLO Mon. raised with 6"

Iron & Cap

WIT: 16" R. Pine N59°E 117.14'

5" R. Pine N51°W 82.93'

SW Cor. of Foundation

S52°E 69.98'

16" B. Oak S72°W 160.81'

L.193, pg. 7518 L. Beauregard

Oct. 1993

Mon-Fd. ½" Bar & Cap

WIT: 18" Norway N59°E 117.14'

20" Tw. Oak N85°W 40.85'

4" Norway N51°W 82.91'

15" Oak S72°W 160.81'

N. Caldwell files

Possible Lucas Wit.

Mon-Fd. GLO

WIT: 1" pipe 33' North

1" pipe 33' West

1" pipe 33' East

SW Bldg. Cor. S52°E 70.98'

18" Oak N79°W 41.89'

T. Pole N44°E 46.97'

14" Oak S42°W 91.60'