

**SURVEY &  
REMONUMENTATION**

SEP 29 1994

COMMISSION

**LAND CORNER RECORDATION CERTIFICATE**  
Filing Requirement of Act 74, Mich. P.A. 1970

STATE OF MICHIGAN  
OSCODA COUNTY  
FILED

For corners in

Oscoda (County)

Located in:

Corner Code ##

14 SEP 94 11:06 A.M.

PATSY J. PETERS  
REGISTER OF DEEDS

1. Public Land Survey

T 26N R 2E

C - 10

2. Property Controlling in Section

S

3. Miscellaneous

S

Property in Sec.

S

4. Lot No. \_\_\_\_\_, Recorded Plat \_\_\_\_\_

5. Private Claims \_\_\_\_\_

I, Marvin E. Myers, in a field survey on July 7, 1994 do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

**NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.**

A. Description of original monument and accessories and/or subsequent restoration:

GLO-July 1839 Coon  
Mon-Post  
WIT: 4" Spruce Pine N17°W 24 lks.  
6" Spruce Pine S19°E 19 lks.  
Near road intersection

April 1911 C.O.Sealey

Mon-Set Post

1947 Lucas

Mon-GLO Cor.

WIT: 8" Birch S50°W 79.20'

6" B.Oak N49°W 75.70'

May 1934 G.D.Henning

Mon-Iron Pin

WIT: NBT 20" Norway S31½°E 1.41 chs.

NBT 16" Norway N58°E 0.80 chs.

GLO-Oct. 1935 Guy Veal  
Mon-3½" Brass Tablet in 6" Conc. Mon.  
WIT: 14" Norway N55½°E 71 lks.  
18" Norway S26½°E 105 lks.  
Near road intersection

Dec. 1963 N.Caldwell

Mon-½" Bar flush with pav't

L.3, pg.447 May 1984 F.King

Mon-Pd. Bar

L.193 pg.199 May 1993 F.King

Mon-Iron & Cap

Sept: 28, 1992 G.G.Wilson Pd. 2" Steel Bar

Checked witnesses Set 2 - 3/8"x30" Std. USFS Mon.

10" Black Oak N28°E 158.72' 12" W.Pine S47°W 73.48'

5" W.Flm S17°E 146.67' 8" W.Pine N36°W 90.31'

LCRC L.1, pg.37 N.Caldwell Dec. 1972  
Mon-½" Bar

WIT: 20" N.P.Stump S29°E 69.20'

10" Jack Pine S42°E 87.50'

12" Oak N50°W 73.60'

1960 Oscoda County Road Comm. Plans

Mon-½"x36" Bar

WIT: NBT 20"-Norway Stump

S28°50'W 69.20'

NBT Spike in 10" J.Pine

S42°E-87.50'

NBT 12" Oak N50°20'W 73.60'

At Station 184+17.6

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner.

Found ½" Bar and Cap #21568 in intersection of roads N - S & E - W. Verified position by measurement to the accessories of record and is accepted as a careful and faithful reestablishment of the position of the original corner. NOTE: Guy Veal did not accept the Henning position. He reestablished the corner position by proportionate measurement and used the scribed NBT of Hennings'. 6" below surface of asphalt directly below ½"x6" bar and cap I found a 3" brass cap #25881 in a 2" pipe (Berntsen type) monument. Set Mon Box.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Mon- 2" pipe with 3" brass cap in mon box.

WIT: Pd. Spike in SW side Power Pole N45°W 41.40'

Fd. USFS Nail & Tag 7" W.Pine N36°W 90.31'

Fd. USFS Nail & Tag 12" W.Pine S47°W 73.48'

Top Center of Concrete triangle shaped project marker N45°E 60.20'

**APPROVED**

County Remonumentation  
Peer Review Group

Signed by Marvin E. Myers

Date Aug-24, 1994

Surveyor's Michigan License No. 31600

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 26, 1977  
REVISED MAY 14, 1977  
REVISED JAN., 1981

L3 Pg 275

A	B	C	D	E	F	G	H	I	J	K	L	M
2	6	5	4	3	2							
3												
4	7	8	9	10	11	12						
5												
6	18	17	16	15	14	13						
7												
8	19	20	21	22	23	24						
9												
10												
11												
12	31	32	33	34	35	36						

