

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

Oscoda _____ (County)

Located In:

Corner Code #

1. Public Land Survey

T 26N R 2E

C - 13

2. Property Controlling

S

In Section

S

3. Miscellaneous

S

Property in Sec.

S

4. Lot No. _____, Recorded Plat _____

5. Private Claims _____

I, Marvin E. Myers, in a field survey on June 13, 1995, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

GLO-L. Clawson May 1839

Mon-Post

WIT: 4" Spruce Pine N18°E 17 lks.

5" Spruce Pine N14°W 34 lks.

G.O. Seeley Sept. 28, 1914

Mon-Fd. point of stake

Set 2' of 3/4" Pipe at

post

WIT: NBT 8" Red Oak N29½°E 2.37 chs.

NBT 11" Red Oak S17°W 3.20 chs.

GLO-1924 Guy Veal

Mon-Set 2"x36" Iron Post proportionate

Wit-10" Norway N18°E 103 lks.

12" Norway N25°15'W 165 lks.

Norm Caldwell April 1964

Mon-Fd. GLO

L.2, pg.132 N. Caldwell Apr. 23, 1969

Mon-Fd. GLO pipe & cap

WIT: USFS Post alongside

8" J.Pine S36°E 75.90'

8" J.Pine S28°W 66.70'

Corner 5 & 6 T24N, R2E is West 33.00'

Center of N-S road East 118.00'

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found US GLO monument and cap. Accepted as a careful and faithful establishment of the position of the corner.

APPROVED

County Remonumentation
Peer Review Group

NCC/31 ~~July~~ 95

APPROVED

County Remonumentation
Peer Review Group

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Mon-US GLO Mon. with Brass Cap

WIT: Fd. nail E. face USFS location post N07°E 42.27'


Fd. nail E. face USFS location post N30°W 55.11'

Fd. nail in N. side utility pole N89°W 75.17'

Nail in N. side utility pole S76°E 89.80'

Monument for 5 & 6, T25N, R2E N83°W 33.00'

Center of N-S road is East 118'±



Signed by

Marvin E. Myers

Date

July 28, 1995

Surveyor's Michigan License No. 31600

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971

REVISED MAY 14, 1975

REVISED JAN., 1983