

SURVEYOR

REGISTERED PROFESSIONAL

APR 11 1995

COMMISSION

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

Oscoda
(County)

Located in:

Corner Code #

1. Public Land Survey

T 25 N R 2 E
T — R —
T — R —
T — R —
T — R —
S — T — R —
S — T — R —
S — T — R —
S — T — R —

2. Property Controlling

in Section

3. Miscellaneous

Property in Sec.

4. Lot No. _____, Recorded Plat _____

5. Private Claims _____

Register of Deeds Stamp & File Number

A	B	C	D	E	F	G	H	I	J	K	L	M
2	6	5	4	3	2	1						
3												
4	7	8	9	10	11	12						
5												
6	18	17	16	15	14	13						
7												
8	19	20	21	22	23	24						
9												
10	30	29	28	27	26	25						
11												
12	31	32	33	34	35	36						
13												

I, Larry G. Beauregard, in a field survey on March 14, 19 95, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:
No corner set on original survey.

1924, Guy R. Veal, Dependent Resurvey, set an iron post, 3' long, 1" diam., 27" in ground, for the North $\frac{1}{4}$ Sec. corner of Section 2, with brass cap.

5-1968, Norman C. Caldwell, P.S. #12018, found U.S. 6L0 pipe & cap at Station 78+89.7'. Raised with 2" pipe & cap flush with pavement. Witnesses marked: (N 65° E 86.6' 8" J. Pine) (N 35° E 38.4' Gov't marker post). South $\frac{1}{4}$ corner of Section 35, T 26 N, R 2 E, is 20.7' East. Recorded L. 2, P. 10, Oscoda County Records Corner Registry.

5-28-1973, Norman C. Caldwell, P.S. #12018, found pipe & cap as perpetuation of U.S. 6L0 monument in accord with Oscoda County Records. No additional witnesses marked. Survey Recorded L. 1, P. 310, Oscoda County Records.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Existing 2" pipe & cap set by Norman Caldwell in 1968 and witnesses mentioned above. Also found 1" pipe with no cap 20.7' East (R) 20.63' East (M), for the South $\frac{1}{4}$ corner of Section 35, T 26 N, R 2 E.



APPROVED

County Remonumentation
Peer Review Group

NCC 16 SEPT 95

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

North $\frac{1}{4}$ corner of Section 2, T 25 N, R 2 E

Oscoda County Remonumentation cap P.S. #18654 on a 5/8" x 18" bar inside a 2" x 12" pipe, this all being inside a monument box. Accepted as a careful and faithful establishment of the position of the corner. Approved by the Peer Group on July 1995.

N 40° E 42.64' Power Pole (Placed P.K. nail & P.S. tag #18654)

N 60° E 86.87' (M) 86.6' (R) 7" J. Pine (Placed 60d penny spike & P.S. tag #18654 above ex. nail & tag by N.C.C.)

South 29.22' Bolt head through steel corner fence post

N 20° E 58.67' 7" Poplar (Placed 60d penny spike & P.S. tag #18654)

Signed by

Larry G. Beauregard

Date

9/8/95

Surveyor's Michigan License No.

18654

Liber 4 pg. 92

STATE OF MICHIGAN
OSCODA COUNTY
FILED

19 SEP 95 4:02 P.M.

PATSY J. PETERS
REGISTER OF DEEDS