

**PRESQUE ISLE COUNTY REMONUMENTATION  
LAND CORNER RECORDATION CERTIFICATE**  
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in PRESQUE ISLE (County) Located in: METZ (Township) Corner Code # \_\_\_\_\_

Instrument 201500000074 OR Liber Page 558 930

- Public Land Survey T 33N R 5E F-11  
T \_\_\_\_\_ R \_\_\_\_\_  
T \_\_\_\_\_ R \_\_\_\_\_  
T \_\_\_\_\_ R \_\_\_\_\_
- Property Controlling in Section S \_\_\_\_\_  
S \_\_\_\_\_  
S \_\_\_\_\_
- Miscellaneous Property in Sec. S \_\_\_\_\_  
S \_\_\_\_\_  
S \_\_\_\_\_

201500000074  
Filed for Record in  
PRESQUE ISLE COUNTY  
CATHY I. IDALSKI, REG OF DEEDS  
01-09-2015 At 09:09 am.  
LC-REMON 14.00  
OR Liber 558 Page 930 - 930

**Register of Deeds Stamp & File Number**

A	B	C	D	E	F	G	H	I	J	K	L	M
2	3	4	5	6	7	8	9	10	11	12	13	14
15	16	17	18	19	20	21	22	23	24	25	26	27
28	29	30	31	32	33	34	35	36	37	38	39	40

I, Daniel T. Kibbe, in a field survey on July 9, 2014, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules thereof as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

**NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.**

**A. Description of original monument and accessories and/or subsequent restoration:**


1855: GLO Set ¼ Sec. Post  
Alfred Millard References:  
Fir 10 N30E 2  
Fir 10 S25W 24

**B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:**

2014: Huron Engineering & Surveying 2014 Remon  
Set 1/2 " rod and standard cap by single proportion. Corner position falls 18'± North & 18'± West of a single hunt wire corner running through trees (no posts) west and south. No other evidence found supporting the fence position

**C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:**

2014: Set 1/2 " rod and standard cap by single proportion  
References:  
N58°W 8.70' 12" Maple set tag # 37278  
N58°E 12.47' 10" Maple set tag # 37278  
S38°E 30.39' 20" Maple (at hunt wire cor) set tag # 37278  
S68°W 30.67' 18" Maple set tag # 37278



Reaffirmed by Peer Group  
in accordance with P.A. 348  
Chairman [Signature]  
Date 11-04-2014

[Signature]

Signed by \_\_\_\_\_ Date November 7, 2014

Surveyor's Michigan License No. 37278