

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in
MONTMORENCY
(County)

Located In: Corner Code #

- 1. Public Land Survey T 32N R 3E M-4, M-5
T R M-6
T R
T R
2. Property Controlling in Section S 12 T R 14
S T R
3. Miscellaneous Property in Sec. S T R
S T R

Register of Deeds Stamp & File Number

- 4. Lot No. , Recorded Plat
5. Private Claims

Grid table with columns A-M and rows 2-13. Contains numbers 1-36 and some dots in the rightmost column.

I, CARL KIISKILA, in a field survey on AUGUST 27, 19 96, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:
M-4 M-5 M-6

(NO EVIDENCE OF G.L.O. CORNER, B.T'S, LINE TREES & TOPOGRAPHY, AS CALLED OUT IN THE G.L.O. LINE NOTES; UNLESS NOTED IN ITEM "B" BELOW.)



B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

- M-4 FOUND 2 1/2" SQUARE CEDAR POST SCRIBED 1/4 SEC" FOR E1/4 COR S-12. NORTH EDGE OF CEDAR BALSAM SWAMP IS 130'+/- NORTH. W1/4 COR S-7, T32N-R4E SET DNR MON IS 500 35'11"E, 230.36'. CORNER FALLS UNDER N-S SMOOTH WIRE.
M-5 REESTABLISHED THE SE COR OF S-12 RECORD US GOV'T. DISTANCE NORTH OF FD SW COR S-7, T32N-R4E AND ON LINE BETWEEN SAID SW S-7 & FD E1/4 COR S-12, T32N-R3E. SMOOTH WIRE TO SOUTH AND WEST. SW COR S-7, T32N-R4E, FD 1/2" REROD & REPLACED W/DNR MON, IS 500°35'11"E, 284.46'.
M-6 REESTABLISHED THE E1/4 COR S-13 S.P. BETWEEN FD SE COR S-13 & REESTABLISHED NE COR S-13 & ON A STRAIGHT LINE BETWEEN SAID FD SE S-13 & FD NW COR S-18, T32N-R4E. CTR OF N-S WINDING SAND TRAIL (ON PRIVATE) IS 61'+/- WEST. N-S SINGLE STRAND OF SMOOTH WIRE ON TREES IS 5'+/- EAST.
14 ESTABLISHED THE NE COR OF THE FRL SE1/4 OF THE FRL SE1/4 OF S-12 PER STANDARD BLM INSTRUCTIONS.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

- M-4 SET 1"x 32" IRON PIPE W/DNR ALUMN CAP & CEDAR POST.
5" MAPLE S37°E 31.58'
5" SPRUCE S53°W 15.87'
5" SPRUCE N29°W 32.11'
7" MAPLE N46°E 24.86'
#W.PINE S47°E 20.12'
#8" SPRUCE N12°W 12.01'
M-5 SET DNR MON & CEDAR POST.
4" SPRUCE N43°W 34.14'
4" MAPLE N36°E 22.19'
3" MAPLE S70°E 14.18'
6" CEDAR S09°W 25.09'
FENCE COR POST N70°W 9.0'
16" PINE STP S75°E 17.3'
M-6 SET DNR MON & CEDAR POST.
8" MAPLE N70°W 31.3'
10" MAPLE N30°W 38.3'
6" MAPLE S10°W 19.7'
7" MAPLE S50°W 40.0'
W1/4 S-18, T32N-R4E, SET DNR MON IS S01°22'23"E 280.39'
14 SET 5/8"x 32" REROD W/PS CAP & ALUMN TAG ON FENCE COR POST, WIRE NORTH & WEST.
6" SPRUCE NORTH 22.78'
5' SPRUCE S88°E 18.16'
8"W.BIRCH S30°E 10.82'
6" MAPLE S55°W 11.56'

# = OLD WIT.

Signed by Carl T. Kiiskila Date 2-27-97

Surveyor's Michigan License No. 33981

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in
MONTMORENCY
(County)

Located In: Corner Code =#

- 1. Public Land Survey T 32N R 3E K-3,
2. Property Controlling in Section S 1 T R 8, 11
3. Miscellaneous Property in Sec. S T R
4. Lot No. , Recorded Plat
5. Private Claims

Register of Deeds Stamp & File Number

I, CARL KIISKILA, in a field survey on JUNE 11, 19 96, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

Grid table with columns A-M and rows 2-13. Contains numerical values and symbols representing a survey grid.

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration: K-3 B 11

(NO EVIDENCE OF G.L.D. CORNER, B.T'S, LINE TREES & TOPOGRAPHY, AS CALLED OUT IN THE G.L.D. LINE NOTES; UNLESS NOTED IN ITEM "B" BELOW.)

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

- K-3: FD IRON W/D. MARLATT P.S. CAP FOR SW COR S-1 (FD 5/8"x 63" REROD ON EAST SIDE OF D.M. IR FOR GUARD IRON).
B: FD D. MARLATT IRON FOR THE NE COR OF THE NW1/4 OF SW1/4 OF SEC. 1. IRON FITS PROPER SUBDIVISION OF SECTION PER STANDARD BLM INSTRUCTIONS.
11: FD IRON ROD FOR THE SE COR OF NW1/4 OF SW1/4 SEC. 1. COR FITS PROPER SUB'D. OF SECTION PER STANDARD BLM INSTRUCTIONS.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner

- K-3: FD 1/2" REROD W/CAP-D. MARLATT. SET 1"x 36" PIPE W/CAP OVER REROD & SET CARSONITE POST.
B: PLACED 1" IRON PIPE OVER FD 1/2" IRON ROD BY D. MARLATT #18660.
11: PLACED 1" IRON PIPE OVER FD 1/2" IRON ROD W/CAP-D. MARLATT #18660.
Bearing and distance measurements for various trees and monuments are listed for each corner type.



Signed by Carl T. Kiiskila Date 2-27-97
Surveyor's Michigan License No. 33981

L-1 P-538

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in
MONTMORENCY

Table with columns: (County), Located In: (Town, Range, Section), Corner Code #. Includes entries for Public Land Survey, Property Controlling in Section, and Miscellaneous Property in Sec.

Register of Deeds Stamp & File Number

- 4. Lot No.
5. Private Claims

Grid table with columns A-M and rows 2-13. Contains numerical data for recording purposes.

I, CARL KIISKILA, in a field survey on JUNE 11, 19 96, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration: L-3, M-3, 15

(NO EVIDENCE OF G.L.D. CORNER, B.T'S, LINE TREES & TOPOGRAPHY, AS CALLED OUT IN THE G.L.D. LINE NOTES; UNLESS NOTED IN ITEM "B" BELOW.)

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

L-3: REESTABLISHED S1/4 COR SEC. 1 PRO-RATED TO US GLO (GEO.H.CANNON - 1851) BETWEEN FD SW S-1 & REESTABLISHED SE COR S-1.
M-3: REESTABLISHED SE COR OF S-1 ON LINE BETWEEN FD SW COR S-6 & NW COR S-6 (T32N-R4E) & PRO-RATED DIST TO U.S. G.L.D., NORTH OF FD SW S-6. N. EDGE OF CEDAR SWP. IS 153' +/- NORTH. CTR OF E-W CO. RD. IS 553' +/- NORTH.
15: ESTABLISHED THE SW COR OF SE1/4 OF SW1/4 S-1 PER STANDARD BLM INSTRUCTIONS. CORNER FALLS IN CUT OVER AREA SMALL POPLAR BRUSH.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

L-3: SET DNR MON & CARSONITE POST. 4" W.PINE S01°E 17.46', 5" W.PINE S74°E 12.19', 5" MAPLE N40°E 33.00', 5" W.PINE N77°W 19.76'.
M-3: SET 1"x 72" IR PIPE W/ALUMN DNR CAP & CARSONITE POST. 6" CEDAR N02°E 5.14', 7" CEDAR S87°E 12.35', 7" CEDAR S17°E 8.80', 6" CEDAR S73°W 9.19', CTR SQD. ASH, 4"x 4" S-SW 0.9' SW COR S-6, T32N-R4E, FD D.MARLATT IR, REPLACED W/DNR MON S01°28'09"E 232.94'.
15: SET 5/8"x 32" REROD W/CAP & CARSONITE POST. 10" W.PINE S36°E 70.14', 12" W.PINE S60°W 73.70', 2" BALSAM N32°W 20.91', 4" W.PINE N10°E 30.58'.



Signed by Carl T Kiiskila 33981 Date 2-27-97
Surveyor's Michigan License No.