

LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in  
ALPENA

(County)

Located In:

Corner Code -#

- 1. Public Land Survey      T 31N R 5E      C-1, C-2, D-1  
    T \_\_\_\_\_ R \_\_\_\_\_      E-1  
    T \_\_\_\_\_ R \_\_\_\_\_  
    T \_\_\_\_\_ R \_\_\_\_\_
- 2. Property Controlling    S \_\_\_\_\_ T \_\_\_\_\_ R \_\_\_\_\_  
    in Section                    S \_\_\_\_\_ T \_\_\_\_\_ R \_\_\_\_\_
- 3. Miscellaneous            S \_\_\_\_\_ T \_\_\_\_\_ R \_\_\_\_\_  
    Property in Sec.            S \_\_\_\_\_ T \_\_\_\_\_ R \_\_\_\_\_

Register of Deeds Stamp & File Number

- 4. Lot No. \_\_\_\_\_, Recorded Plat \_\_\_\_\_
- 5. Private Claims \_\_\_\_\_

A	B	C	D	E	F	G	H	I	J	K	L	M
2	6	5	4	3	2	1						
3												
4	7	8	9	10	11	12						
5												
6	18	17	16	15	14	13						
7												
8	19	20	21	22	23	24						
9												
10	30	29	28	27	26	25						
11												
12	31	32	33	34	35	36						
13												

I, CARL T. KIISKILA, in a field survey on NOVEMBER 1, 19 94, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

C-1	C-2	D-1	E-1
(NO EVIDENCE OF G.L.O. CORNER, BT'S, LINE TREES & TOPOGRAPHY, AS CALLED OUT IN THE G.L.O LINE NOTES; UNLESS NOTED IN ITEM "B" BELOW.)			

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

C-1	C-2	D-1	E-1
FOUND LARGE SPIKE, FOR THE NW CORNER OF SEC. 5, REPLACED WITH 5/8" x 32" REROD. OLD FENCE LINE DUE SOUTH OF CORNER.	REESTABLISHED W 1/4 COR SEC 5 MIDWAY AND ON LINE BETWEEN FOUND SECTION CORNERS WHICH AGREES WITH SURVEYS DONE IN SECTION 6.	ACCEPTED FD 1/2" PIPE IN CTR ROAD	ACCEPTED FD 1/2" ROD WITH L.S. CAP NO. 31591

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

FOUND LARGE SPIKE REPLACED WITH 5/8" x 32" REROD.	SET DNR MON AND CEDAR POST 6" BASSWOOD S85°E 13.86'	FD 1/2" PIPE SET CEDAR POST WITH TAG	FD 1/2" ROD WITH CAP 10" BALSUM S37°E 34.92'
STOP SIGN POST N05°W 63.71'	7" BASSWOOD N35°W 15.94'	22" SPRUCE S10°E 47.11'	4" SPRUCE S55°W 43.93'
GTE SIGN POST N28°E 63.96'	14" BASSWOOD N65°W 11.11'	8" J. PINE N29°E 52.48'	6" TWIN SPRUCE S80°W 76.16'
GTE SIGN POST S10°E 34.52'	6" BASSWOOD S30°E 1.29'	6" J. PINE N35°W 43.93'	CEDAR POST NORTH 34.02'
DRILL HOLE IN S. END OF CMP		14" BASSWOOD S52°E 63.55'	CTR E-W CO RD NORTH 4.5'
CULVERT S81°W 59.75'		PIPE IS LOCATED AT THE CTR OF E-W CO RD	
CTR E-W CO RD NORTH 2.0'			
CTR RD TO N. EAST 2.0'			

Signed by Carl T. Kiiskila Date 1-25-95  
Surveyor's Michigan License No. 33981

