

HISTORY CONTINUED:

1958 MCRC Road Plans show corner & wit's, marked (6) N22°-30'W 48.1' 26" P. Stump (7) S23°W 127.7' 24" Oak.

1966-67 Norman C. Caldwell P.S. #12018 found Rec. 1/2" bar, Sec. corner from Smith & De La Mater, while doing a Sec. divisional survey of Sec. 20. Wit's found 3, 5, 6 & 7. Prepared two Act 132(s) (Not recorded).

Circa 1970(s) Kenneth J. Ostling P.S. #10068 (DNR Surveyor) found this corner as shown on Twp. diagram. No description or wit's.

1972 Larry G. Beauregard P. S. #18654 (Surveyor for R. S. Scott Eng. Co. Inc.), found Rec. corner established by other surveyors. Filed Act 132, Rec. L. 1, Pgs. 170 -175. No new wit's. marked.

1974 L.G.B. (Surveyor for Scott) found 1/2 " bar & RLS cap. Filed Act 132, Rec. L. 1, Pgs. 544-546. Wit's. marked (8) S70°W P. Pole 75.9' (9) S70°E Project Marker 73.3' (10) North 33' DNR Post & tab.

1979 L.G.B. (Surveyor for Scott) found 1/2 " bar, with cap & wit's. 8 & 9. Prepared Act 132. (Not Recorded) Wit. Marked (11) North 33' 1/2 " bar & DNR Post.

1997 L.G.B. (Surveyor for Scott) found 1/2 " bar 1' S. +/- of Rd. C/L while doing a survey for MCRC on Co. Rd. 612. See sheets 19 & 20 of plans for wit's.

Jan.

2008 Ronald C. Brand P.S. # 43046 found 1/2 " bar at corner. Wit's. found & measured (11) N08°E 32.94' 1/2" bar & cap # 12018. Wit's marked, (12) S59°W 54.90' 12" W. Pine (13) N08°E 33.31' DNR Post. (14) N35°W 53.56' 12" Poplar.

May

2008 Brent C. Clough P.S. #52264, found 1/2 " bar 1' +/- South of Co. Rd. 612 C/L & C/L of Granholm Rd. South. Preserved corner position due to Rd Const. Condition of previous wit's. (1) & (2) gone. Wit's found 11- 14. Wit. Marked (15) S31°E 66.16' Top Bolt of Vertical Gas Line Pipe. Filed LCRC Rec. L. 1, P. 710.

