SURVEY & CHEBOYGAN COUNTY REMONUMENTATION CORNER

FEB 2 6 1998	LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970
	1

16041 Toression

For corners in	12 10.0.
CHEBOY SECTION Located In: Corner Code #	RECEIVED FOR RECORD 218 9
(County) 3BN 2W B-13	at
1. Public Land Survey	- Janne Spray
TR TR	-
2. Property Controlling S T R	- CLERK/REGISTAR
in Section S T R	- CARLON CAN COUNTY, MICHIGAN
Property in Sec. S TR	Register of Deeds Stamp & File Number
4. Lot No, Recorded Plat	A B C D E F G H I J K L M
,	2 6 5 4 3 2 1 1
LIAMES H. GRANGER in a field survey on JULY 15	3 3 9 97 do hereby state 4 7 8 9 10 11 -12
I, <u>JAMES H. GRANGER</u> , in a field survey on <u>JULY 15</u> , 1 that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned were in conformance with regulations and rules therefore as required in the curr	entimanual of Survey
instructions of the United States Department of the Interior, Bureau of Land Managem Court of Law and for that the corner points mentioned in lines 3, 4 and 5 above were in	ent or by a decree of a 6 18 17 17 17 18 18 18 18 18 18 18 18 18 18 18 18 18
rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law, estal monumented, recovered, found as expressed below:	blished, re-established, 8 19 20 21 22 23 24
NOTE: Not more than 2 corners, all in the same town and range, may be rec	orded 9
on this certificate.	10 30 29 28 27 26 25
	11 32 33 34 35 36
A. Description of original monument and accessories and/or subsequent re	storation:
B-1 1840 Original Survey John Mullett Set wood post 40" Hemlock 12" Birch	N45°W 11 lks N42°E 10 lks
1972 Survey Metal Monument Orlando Doyle #7319	Chen
1977 LCRC 1 1/4" Pipe Orlando Doyle #7319	SEP 2 5, 1997
1985 Survey Metal Monument Orlando Doyle #7319	James Harris
	To have the same of the same o
	Conum soils
B. Description of corner evidence found and/or method applied in restoring	
B-1 No evidence of monument found. Found 2 witnesses, grown over, per remonumentation cap per existing witnesses.	r Doyle LCRC. Set 5/8" rebar and
C. Description of monument for corner and accessories established to perp	etuate locating the position of the corner:
B-1 5/8" rebar and Remonumentation Cap	*
14" Pine S52°W 43.27' Set tag #16041 PP S 6°W 31.79' Set tag #16041	
14" Pine N50°E 44.46' Set tag #16041 8" Pine N28°W 22.52' Set tag #16041	LIBER 011 PAGE 24
l a of the man	Date Nov. 17, 1997 Surveyor's Michigan
Signed by James 14 Knanger	Date / VV / / / / / Surveyor's Michigan
License No. 16041 OF MICHIGAN PORM APPL	
JAMES H.	ROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971 REVISED 14,1876
GRANGER \	REVISED JAN., 19. REVISED OCT., 19.
JAMES H. GRANGER PROFESSIONAL SURVEYOR NO.	•
数 化 》	