LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

	FOR CORNERS OF -:	LOCATED IN -:	CORNER CODE NUMBER	1	
	1. PUBLIC LAND SURVEY	. T N. R E. W.			
	2. PROPERTY CONTROLL- ING IN SECTION—9	,T. 41 N. R. 24 E.	_14, 15, 16		
,	3. MISCELLANEOUS PROPERTY IN SECTION	,T N., R E.			
	4. LOT NO, RECO	RDED PLAT			
	5. PRIVATE CLAIMS			REGISTER OF DEEDS STAMP AND FILING NUMBER	
	the corner points mentioned in lines 1 and 2 above (identified with circles on index code diagram—over) were, in a field survey on October 31 19 78, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3,4 and 5 above were, in a field survey on 19—, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:				
14	A. Description of original monument and accessories and/or subsequent restoration: - 8 1/16 corner on E. line of Section 9; not previously established.				
15	15 - W 1/16 corner on the South line of Sec. 9; not previously established.				
16 - East 1/16 corner on the south line of Sec. 9; not previously established.					
B. Description of corner evidence found and/or method applied in restoring or re-establishing corner: 14 - Set M.P.O.L. between the E. & corner and the S.E. section corner of Sec. 9.					
15	15 - Set M.P.O.L. between the south & corner and the S.W. section corner of Sec. 9.				
16	16 - Set M.P.O.L. between the S & corner and the S.E. section corner of Sec. 9.				
		, .		in- shision of she corner	
1 4	C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: ALL - 1" pipe, 4" aluminum cap. 14 - 4" Spruce - N89°E - 19.4"; 6" Tam S12°E - 14.3'; 5" Spruce - S51°W - 19.0'; 8" Tam West - 42.0'				
15	- 6" B. Spruce - S81°W - 9.3'; 8" Aspen - N5°W - 22.9'; 10" Balsam - N87°E - 29.2'; 14" B. Spruce - S36°E - 10.0'				
16	- 5" Tam S64°E - 23.7'; 6" Spruce - S51°W - 37.4'; 6" Tam N78°E - 47.55'; 8" Tam N10°W - 64.8'; Centerline of ditch - South - 11'				
	SIGNED BY	IGNED BY DATE			
	SURVEYOR'S MICHIGAN REG	GISTRATION NO		(SEAL)	
	FOR STATE AND UNITED ST	ATES AGENCIES:			
	SIGNED BY	CHIEF OF AURVEY PARTY	DATE	· · · · · · · · · · · · · · · · · · ·	
	APPROVED AND SIGNED BY	Lavid B. K	Ballet DATE -	11-13-78	
				(SEAL)	

ş.