



Facility Summary Report

Building Name: *Muskallonge Lake State Park/Electric System W Campground*

DNR TagID#: *82507*

Facility Location: *Muskallonge Lake State Park*

Inventory Status: *Verified*

Inventory Date: *07/01/2016*

Managing Agency: *Parks and Recreation*

Facility Type: *Utility Support*

Facility Use: *Electrical Distribution System*

Building Status: *Active*

Building Manager: *Jim Dzelak (906-658-3338)*

Building Telephone: *906-658-3338*

Building Fax: *906-658-3365*

Building Address: *Unknown*

Construction Date: *10/10/1970*

Square Footage: *0*

Historical Cost: *\$60,000*

Leased/Own: *DNR-Owned*

NO PHOTO AVAILABLE

Employees at Location: *No*

Vacant Workstations: *None*

Electricity: *No*

Water: *No*

Heat: *No*

Storage Space: *No*

MISC. COMMENTS

This system is in very poor condition. 9 campsites are without power for the 2016 season due to safety issues of the old equipment.

LOCATION INFORMATION

COUNTY NAME	TIER/RANGE	TOWNSHIP NAME	SECTION	QQ	Q	LOTS PAR ID	LATITUDE	LONGITUDE
Luce	50N - 08W	MC MILLAN	01	SW	NW		46.67510500	-85.63144800