



# Facility Summary Report

*Building Name: Gaylord Repair Shop/Fmfm Gaylord Repair Shop*

**DNR TagID#:** 83956  
**Facility Location:** *Gaylord Repair Shop*  
**Inventory Status:** *Verified*  
**Inventory Date:** *07/14/2016*  
**Managing Agency:** *Forest Resources*  
**Facility Type:** *Storage/Workshop*  
**Facility Use:** *Workshop/Lab*  
**Building Status:** *Active*  
**Building Manager:** *Dennis Francis (989-732-4481)*  
**Building Telephone:** *989-732-4481*  
**Building Fax:** *989-705-8069*  
**Building Address:** *Unknown*  
**Construction Date:** *12/11/2000*  
**Square Footage:** *12,800*  
**Historical Cost:** *\$1,309,229*  
**Leased/Own:** *DNR-Owned*



**Employees at Location:** *Yes - 4*  
**Vacant Workstations:** *Yes - 0*  
**Electricity:** *Yes*  
**Water:** *Yes*  
**Heat:** *Yes*  
**Storage Space:** *Yes - Heated*

### MISC. COMMENTS

*Repair facility for DNR heavy equipment. Public visitors limited to VFD's and customers of GSA and MI-Bid auctions.*

### LOCATION INFORMATION

COUNTY NAME	TIER/RANGE	TOWNSHIP NAME	SECTION	QQ	Q	LOTS PAR ID	LATITUDE	LONGITUDE
Otsego	31N - 03W	LIVINGSTON	32	SW	SW	125422	45.02842068	-84.71086257