



# Facility Summary Report

*Building Name: Roscommon Forest Management Unit/Ambrose Lake Restoration*

DNR TagID#: *84727*

Facility Location: *Roscommon Forest Management U*

Inventory Status: *Verified*

Inventory Date:

Managing Agency: *Forest Resources*

Facility Type: *Land Improvements*

Facility Use:

Building Status: *Active*

Building Manager:

Building Telephone:

Building Fax:

Building Address: *Unknown*

Construction Date: *06/18/2010*

Square Footage: *Unknown*

Historical Cost: *\$392,415*

Leased/Own: *Unknown*

Employees at Location: *Unknown*

Vacant Workstations: *Unknown*

Electricity: *Unknown*

Water: *Unknown*

Heat: *Unknown*

Storage Space: *Unknown*

NO PHOTO AVAILABLE

## MISC. COMMENTS

## LOCATION INFORMATION