



Facility Summary Report

Building Name: Mount Clemens PRD Field Office/Selfridge BAS Sewall Repairs

DNR TagID#: **84874**

Facility Location: **Mount Clemens PRD Field Office**

Inventory Status: **Verified**

Inventory Date: **3/23/2017**

Managing Agency: **Parks and Recreation**

Facility Type: **Land Improvements**

Facility Use: **Boat Access Site**

Building Status: **Active**

Building Manager: **Duane Askew (586-465-2138)**

Building Telephone: **586-465-2138**

Building Fax: **586-465-2142**

Building Address: **Unknown**

Construction Date: **7/23/2013**

Square Footage: **Unknown**

Historical Cost: **Unknown**

Leased/Own: **DNR-Owned**

NO PHOTO AVAILABLE

Employees at Location: **Unknown**

Vacant Workstations: **Unknown**

Electricity: **Unknown**

Water: **Unknown**

Heat: **Unknown**

Storage Space: **Unknown**

MISC. COMMENTS

CAPITALIZED LAND IMPROVEMENT PROJECT INVENTORIED AS PART OF YEAR-END REPORTING PROCESS.

LOCATION INFORMATION

COUNTY NAME	TIER/RANGE	TOWNSHIP NAME	SECTION	QQ	Q	LOTS PAR ID	LATITUDE	LONGITUDE
Macomb		HARRISON					42.63123900	-82.81774200