


MICHIGAN DEPARTMENT OF CONSERVATION
CARNEY LAKE

AREA 117 ACRES
 DICKINSON COUNTY T. 41 N., R. 29 W., SECS. 33, 34
 T. 40 N., R. 29 W., SEC. 6
 SURVEY AND SOUNDINGS FEB. 13, - FEB. 17, 1961



B.M. No. 3=100.0-TOP OF SECTION
 CORNER MARKER
 WATER SURFACE ELEVATION=96.6
 2/17/61

B.M. No. 2=100.0-SPIKE IN BASE
 OF 6" DI TRUNKED ASH
 WATER SURFACE ELEVATION=95.6
 2/17/61

B.M. No. 1=100.0-SPIKE IN BASE
 OF 6" WHITE PINE
 WATER SURFACE ELEVATION=93.1
 2/17/61

WATER
 ACCESS
 SITE

TO BENTONS LAKE

LEGEND

BOTTOM

- Sand
- ▨ Organic
- ⊘ Gravel
- ⊙ Rock

SHORE FEATURES

- ⋈ Encroaching shore
- ≡ Steep slope
- Ⓜ Wooded
- + Brush
- ⊕ Marsh
- Building
- Improved road
- Inlet or outlet
- ⊘ Beaver house

