

MICHIGAN DEPARTMENT OF NATURAL RESOURCES
JOHNS LAKE, EAST


AREA 20 ACRES

ALGER COUNTY

T. 48 N., R. 13 W., SEC. 26

SURVEY AND SOUNDINGS

DEC. 22 - DEC. 23, 1966



B.M. No. 2=100.8 - SPIKE IN BASE
 OF 22" WHITE PINE
 WATER SURFACE ELEVATION=97.1
 12/23/66

B.M. No. 1=1000 - SPIKE IN BASE
 OF 16" 19" TWIN PINE
 WATER SURFACE ELEVATION=97.1
 12/23/66

B.M. No. 3=100.1 - SPIKE IN BASE
 OF 16" WHITE PINE
 WATER SURFACE ELEVATION=97.1
 3/23/66

LEGEND

BOTTOM

- Sand
- Organic
- Deadhead

SHORE FEATURES

- Encroaching shore
- Steep slope
- Wooded
- Partly wooded
- Marsh
- Unimproved road
- Foot trail
- Inlet or outlet
- Beaver dam

