


B.M.=100.0-R.R.SPIKE BASE  
 OF ELM TREE,  
 S.W. OF LAKE.  
 WATER SURFACE ELEV.=97.4  
 1/18/44

**TISH LAKE**  
 AREA 5.8 ACRES  
 MARGINAL SURVEY AND SOUNDINGS INVENTORY 1/17, 18, 19/44  
 7/18, 19/44  
 JACKSON COUNTY T. 1 S., R. 2 E., SEC. 29



- LEGEND**
- BOTTOM**  
 [Stippled] Marl  
 [Cross-hatched] Marl and Muck
- OUTLINE & CONTOURS**  
 [Solid line] Shoreline  
 [Dashed line] Contours
- SHORE FEATURES**  
 [Wavy line] Marsh  
 [Downward arrow] Brush  
 [Wavy line with dots] Encroaching shore  
 [Circle with cross] Wooded  
 [Circle with dot] Partly wooded  
 [Line with arrow] Inlet  
 [Line with arrow] Outlet  
 [Line with arrow] Deadhead
- VEGETATION**  
 [T] Floating  
 [I] Emergent  
 [-] Submergent
- STATIONS**  
 [Circle with dot] Vegetation  
 [Triangle with dot] Temp., chem., plankton  
 [Square with dot] Bottom sample  
 [Circle with X] Fish sample

LITTLE PORTAGE LAKE

B.M.=100.0-R.R.SPIKE BASE  
 OF TREE, NORTH  
 POINT OF ISLAND,  
 S.E. SIDE OF LAKE.  
 WATER SURFACE ELEV.=94.9  
 1/18/44

